

MISSOUR! DEPARTMENT OF NATURAL RESOURCES 8460 Watson Road St. Louis, Missouri 63119 (314) 849-1313

3.600 St. Louis County West Lake Landfill, Inc. Demolition Landfill *MRD07994933 *MRD07994933 *** 17.8. **** 17.8.

recorded

RECEIVED

MAR 28 1978

BUREAU OF GOLD WASTE MANAGEMENT

March 24, 1978

Mr. William Canney West Lake Landfill, Inc. Route 1 Box 206 Bridgeton, Missouri 63042

Dear Mr. Canney:

On March 9, 1978, a quarterly re-inspection of the West Lake Landfill Inc. Demolition Landfill was made by representatives of the Missouri Department of Natural Resources. As a result of the inspection, the following observations were made.

UNSATISFACTORY FEATURES:

None.

COMMENTS:

Demolition materials were being dumped at the top of the working face, pushed over the edge of the face, and compacted down the face of the slope. Cover material was dumped at the bottom and worked back up the face of the slope. The operator stated that this method of spreading and compacting was used to minimize damage to the undercarriage of the compacting machine. His experience had shown that when they spread, and compacted bulky items such as large blocks of concrete and large stumps from the toe of the slope up the working face of the landfill, it was difficult for the machine to climb over the materials and frequently the undercarriage sustained damage from the effort.

Some cardboard was observed among the demolition materials. If at all possible, such excluded wastes should be diverted to the sanitary landfill.

RECOMMENDATIONS:

Segregate excluded wastes such as cardboard at the check in station and re-route them to the sanitary landfill.

40241255

SUPERFUND RECORDS

Joseph P. Teasdale Governor Carolyn Ashford Director St. Louis Regional Office

DNR 0100

Page Two Mar. 24, 1978

If you have any questions, please give us a call at our St. Louis Regional Office.

APPROVED:

SUBMITTED BY:

Earl F. Holtgraewe, P.E. Regional Administrator St. Louis Regional Office Department of Natural Resources Howard J. Winburn
Environmental Engineer I
St. Iouis Regional Office
Department of Natural Resources

EFH/HJW/ec

CC: Paul H. Himebaugh, Suite 257, 9929 Manchester Road, Warson Woods, MO Earl Breadon, 2337 Telegraph Rd., Lemay 63125
Ray Snider, Department of Community Health and Medical Care 801 South Brentwood Boulevard, Clayton, MO 63105
Central Office, Solid Waste Program

MISSOURI DEPARTMENT OF NATURAL RESOURCES DIVISION OF ENVIRONMENTAL QUALITY

DEMOLITION LANDFILL SURVEILLANCE RECORD

Date:3/9/7.8	Days	Week Open:	5.1/2	
Name of Demolition Landfill: West La	ke La	and fill, I	c Dem	lition Land
Permit No: 218903	Cour	ity: <u>\$7 / c</u>	0014	
Owner: West Lake Landfilly				
Address: Route 1, Box 206	Addr	ess: Route	1, Box	206
Address: Route 1, Box 206 Bridgeton, Mo 636	<u> </u>	Bridge	ton, Mo	63042
Special Conditions and Approved Modification			•	
A. Are there any special conditions or approve the rules and regulations? (e.g. impermea quirements)	ble barrier,	limited excavation	, exceptions to	
	Yes	No		•
B. Is the demolition landfill operation in comp (If "No," describe violations under "REMA	ARKS.")	•		d modifications?
II. Check Types of Waste Accepted				
		INDICATED ON PERMIT APPLICATION	REPORTED BY OPERATOR	AS DOSERVED -
Demolition and construction waste				1
Brush and untreated wood waste			<u> </u>	
Tires		· · · · · · · · · · · · · · · · · · ·	 	
Inert Plastics			\	 -
			ł	
OTHER WASTES (SPECIFY)		<u> </u>		 -
·	-			
		·		
		·····		
\ 			<u> </u>	-
II. Remaining Life of Landfill				
A. Estimated average volume of compacted s		received. , yards/day, wash)		
B. Estimated volume of remaining landfill cov		proved engineering acre feet	plans. RECE	INES
			MAR 2	* * E.U B 1978
			SOLIO WASTE MAI	

SUBSECTION NUMBER	SATISFACTORY COMPLIANCE OPERATING PROCEDURE	SAT	uns	SUBSECTION NUMBER	SATISFACTORY COMPLIANCE OPERATING PROCEDURE	SAT	Uř
(2) SOLID W	ASTE ACCEPTED	-		(10) AESTRET	C\$ (continued)		
(2)(C)I	Routine sanitary landfill techniques of spreading and compacting solid waste shall be used as much as practicable to dispose of			(10)(C)4	Salvaged materials removed daily or stored in aesthetically acceptable manner.		E
	solid waste in a demotition tandfill.	╀╌┥		(11) COVER M	ATERIAL		
(2)(C)2	A first of wastes to be accepted shall be displayed prominently at the site entrance.	1		(11)(C)1	Twelve (12) inches compacted soil cover material applied at least once every seven catendar days.		F
(3) SOLID W	ASTE EXCLUDED			(11)(C)2	Final cover of at least two (2) feet compacted soil applied on all		\vdash
(3)(C)1	A responsible supervisor shall be present at the disposal area at all times when the area is open to receive waste.	-		(12) COMPACT	completed areas.		
(3)(C)2	Excluded wastes deposited removed to an approved disposal site.	ᅥᆔ		(12)(C)1A		Т	Т
(4) SITE SEL				(IZ)(U)IM .	Solid waste spread in layers not to exceed two (2) feet as much as practical.		T
(4)(C)	Site accessible by all-weather roads.	\Box		(12)(C)18	Solid waste compacted to smallest practical volume.	_	扌
(6) WATER (WALITY			(12)(C)1C	Cover material compacted as much as practical.	-	Г
(6)(C)1	Surface water courses and runoff satisfactorily diverted from the landfill. Demolition landfill construction and grading to promote rapid surface water runoff without excessive erosion.			(12)(C)2	Equipment avaitable and operated to spread and compact the solid waste as received or at least when the accumulated waste reaches 200 cubic yards.	-	Γ
(6)(C)2	Decomposable solid wastes deposited above predicted maximum water table.	V		(12)(C)3	No solid waste disposed of in water where the water interfered with spreading and compacting or where the water is causing a mos- quito problem.	-	T
(7) AIR QUAI	uity		<u> </u>	(13) SAFETY	data hansin	1	ᆫ
(7)(¢)	No open burning without written permission from the agency hav- ing jurisdiction.			(13)(C)1	Fire extinguishers provided on all equipment.	Ī	F
(8) GAS COM	TROL			(13)(C)2	Provisions for extinguishing fires in waste, equipment or struc-	,	匸
(8)(C)1	Decomposition gases adequately vented to prevent danger to occu-				lures.		
	pants of adjacent property.			(13)(C)3	Scavenging prohibited.	1	丰
(8)(C)2	Gases vented to prohibit explosive or toxic accumulations.			(13)(C)4	Controlled access limited to operating hours.	<u> </u>	ļ_
(9) VECTORS				(13)(C)5	Traffic control signs provided.	<u></u>	1
(9)(C)	Vector control programs implemented when necessary.	<u> </u>		(13)(C)6	Dust control adequate.		<u> </u>
(10) AESTHETI	<u> </u>	·		(14) RECORDS			
(10)(C)1	Litter collected and compacted into cell be utilized daily.	<u>'-1</u>		(14)(C)1A	Records of complaints and major problems.	<u> </u>	-
(10)(C)2	Wastes easily moved by wind covered as necessary.	1		(14)(C)1B	Records of dates of cover material application.		
(10)(C)3	On-site vegetation and natural windbreaks being utilized for litter			(14)(C)1C	Records of vector control efforts.	<u> </u>	F
	control and aesthetic appearance.			(14)(C)10 ·	Records of dust and litter control efforts.		
				(14)(C)1E	Records of quantity of waste received.	سسنا	f T
				(14)(C)2	Records of location of general types of wastes and depth of fill.	·	-
							_

~			es	No	demolition	u za l o a
MARKS <u>Some</u>	Cara Bbara		<u> </u>			
1 site. The	: cliff_	meth	od of	dump	ng and	50read
he solid	Wastes:	WES	,		1.	
•		• .	- J/			
					···	